

From glowbugs@theporch.com Thu Aug 1 17:59:43 1996  
Return-Path: <glowbugs@theporch.com>  
Received: from uro (localhost.theporch.com [127.0.0.1]) by uro.theporch.com  
(8.8.Alpha.7/AUX-3.1.1) with SMTP id RAA25453; Thu, 1 Aug 1996 17:56:08 -0500  
(CDT)  
Date: Thu, 1 Aug 1996 17:56:08 -0500 (CDT)  
Message-Id: <199608012256.RAA25453@uro.theporch.com>  
Errors-To: ws4s@midtenn.net  
Reply-To: glowbugs@theporch.com  
Originator: glowbugs@theporch.com  
Sender: glowbugs@theporch.com  
Precedence: bulk  
From: glowbugs@theporch.com  
To: Multiple recipients of list <glowbugs@theporch.com>  
Subject: GLOWBUGS digest 250  
X-Listprocessor-Version: 6.0c -- ListProcessor by Anastasios Kotsikonas  
X-Comment: Please send list server requests to listproc@theporch.com  
Status: 0

#### GLOWBUGS Digest 250

Topics covered in this issue include:

- 1) Soldering to Aluminum  
by "Barry L. Ornitz" <u856010@eastman.com>
- 2) Re: Soldering to Aluminum Chassis  
by John Kolb <jlkolb@cts.com>
- 3) Transformers and thanks for Soldering Advice  
by Chris Broadbent <cfb@bga.com>

-----  
Date: Wed, 31 Jul 1996 20:39:41 -0400 (EDT)  
From: "Barry L. Ornitz" <u856010@eastman.com>  
To: glowbugs@theporch.com  
Cc: Chris Broadbent <cfb@bga.com>  
Subject: Soldering to Aluminum  
Message-ID: <Pine.ULT.3.91.960731200912.715A-1000000@dua150.kpt.emn.com>

On Wed, 31 Jul 1996, Chris Broadbent asked about soldering to aluminum in preference to using grounding lugs with star lockwashers.

> The TX is based on a tube (6LR8). I plan on mounting everything on an  
> aluminum chassis with point to point wiring underneath, using tag strips and  
> the tube and relay sockets as anchor points.

I am not sure by what Chris means by "tag strips" unless these are what most folks call terminal strips. Most terminal strips were screw mounted

to the chassis anyway and the lug provides a convenient ground.

> I would like to use the chassis as the common or ground. Rather than using  
> nuts, bolts and spikey spring washers, I would prefer to solder to common  
> returns to the chassis. I believe I'll get a better, longer term connection  
> if this is possible (am I wrong?).

It is POSSIBLE but not at all practical. Aluminum will solder using ordinary tin/lead solders if the proper flux is used. Because aluminum is always covered by a protective layer of its oxide, the flux must be quite aggressive. Adding copper to the joint is asking for trouble. Not only do you have a rather bad electrochemical couple for corrosion, the intermetallic compounds of aluminum/lead/tin/copper are unstable. I have never seen an aluminum to copper soldered joint last more than a few months if it was kept extremely dry. With moisture present, expect the joint to fail within hours to days.

>From a construction standpoint, it is generally not necessary at frequencies below 30 MHz to need such extremely short ground leads. At VHF and above, it is common to use copper or brass to facilitate the grounding.

> I have a 40W temp. controlled iron (Ungar) and a dirty great 140W Weller  
> soldering gun. Is it reasonable/possible to solder the copper wire directly  
> to the aluminum chassis with one of these irons and get a good connection?

No. In fact, soldering aluminum with them with the proper flux may ruin the tips for future soldering of copper.

> If this is not practical, has anyone any suggestions? I can get a steel  
> chassis, but I'm a little reluctant to do this (cost and difficulty of  
> punching the many holes I'll need).

A steel chassis provides more mechanical strength but you will find soldering directly to one often takes more heat than your tools provide. The aluminum is lighter, does not rust, and is far easier to work with. Most folks find that a large assortment of small nuts and bolts is an invaluable asset when homebrewing radio gear. Star lockwashers are designed to bite into the aluminum and pierce the oxide layer insuring a good electrical connection. Just make sure the screws are tightened properly.

Another approach to be considered is to use a sheet of printed circuit copper-clad laminate - either as the chassis itself, or as an added layer over the aluminum inside the chassis. The foil can be grounded to the chassis with several screws and you can solder to the foil.

To go back to aluminum soldering, I would like to add that the "miracle

rod" sold at hamfests for aluminum soldering is basically a big rip-off. Instead of "20 or more exotic metals in the alloy", the rod is basically zinc with about 20% aluminum and a trace of copper as a contaminant. Zinc, when molten, has an extremely low viscosity; it flows over aluminum well and fills in surface pores and pits in the oxide layer. It makes what appears to be a soldered connection, but the true alloying needed in soldering/brazing is not present. Can you repair things with this rod? Of course, but do not expect particularly high strength or exceptionally long life if the joint is exposed to moisture. Zinc is pretty cheap too!

73, Barry L. Ornitz WA4VZQ ornitz@eastman.com

-----  
Date: Wed, 31 Jul 1996 17:53:02 -0700 (PDT)  
From: John Kolb <jlkolb@cts.com>  
To: Chris Broadbent <cfb@bga.com>  
Subject: Re: Soldering to Aluminum Chassis  
Message-ID: <Pine.SCO.3.91.960731174748.26967A-1000000@sd.cts.com>

On Wed, 31 Jul 1996, Chris Broadbent wrote:

> I have a 40W temp. controlled iron (Ungar) and a dirty great 140W Weller  
> soldering gun. Is it reasonable/possible to solder the copper wire directly  
> to the aluminum chassis with one of these irons and get a good connection?

>  
In spite of the claims of magic solder fluxes, I would say NO (not NO,  
but HELL, NO).

> If this is not practical, has anyone any suggestions? I can get a steel  
> chassis, but I'm a little reluctant to do this (cost and difficulty of  
> punching the many holes I'll need).  
>

One method would be to get a roll of adhesive backed copper foil.  
Tape that onto the chassis along the paths you would follow if  
you were using a wire to interconnect all the gnd points - then solder  
the component lead to the copper foil. Solder the foils together  
wherever two foils join or cross each other.

I mostly build stuff on PC board material, and thus have a continuous  
copper surface for ground.

73's

John Kolb KK6IL

-----  
Date: Thu, 1 Aug 1996 00:00:41 -0500 (CDT)  
From: Chris Broadbent <cfb@bga.com>  
To: glowbugs@theporch.com  
Subject: Transformers and thanks for Soldering Advice  
Message-ID: <199608010500.AAA28864@zoom.bga.com>

<many, many replies saying DON'T solder to aluminum>

Thank you all for the advice. I was a little uncertain about the star washer, nut and bolt method of connecting to the chassis. It seems this is the preferred method by far. I shall use this method instead.

Thanks again for the advice.

BTW, I found the transformer I needed. There is a gentleman in the area (Austin, TX, USA) who used to own & maintain hospital room TV's. He has a warehouse full of them, along with tools, valves/tubes and all sorts. He wants to empty out the warehouse (300 or so TV's - many are semiconductor with a number of hybrids and a few full blown tube TV's). He's not that interested in the small onesy-twosy liquidation, as it's quite far out of town. So if anyone is in the area and would like to go shares with me on collecting the junk, let me know. He said he would liquidate everything for about \$300 (there is really a lot of stuff). I can't take that much stuff - my wife'd shoot me.

So, I have this transformer with no value markings. This is how I figured the maximum I could load the various coils.

First I measure the coil resistances and map out the taps.

Then, taking a guess that the black-black/red pair is the primary (the coil resistance making it a fair guess), I connect it and find the voltages across each coil and tap.

- I weigh the transformer and go through all my catalogs for transformers of similar weights with listed secondary V & A ratings. From this I determine the W/lb. There is a close correlation across the 8 or so samples I found. I multiply the W/lb rating (15W/lb for my samples) with my transformer's weight (~6.5 lbs), giving a maximum rating for my transformer (~100W).

- I know that the wattage delivered by each secondary is proportional to the voltage across it. Likewise, the maximum wattage deliverable is inversely proportional to the coil resistance (due to coil heating). So I come up with a Volts/Ohm value for each secondary. I add these together and use the total to determine what ratio of the transformer's maximum power rating each

coil/tap takes. I assume that inductance heating losses are minor, given what I know about transformer efficiencies.

- With this watt value and the voltage for each coil/tap, I can determine the maximum deliverable current. Just as a sanity check, I use this current value and the coil resistance to determine how many watts would be dumped by each secondary/tap into the transformer.

The coil combinations I need all can deliver over twice my required current according to these calculations. So there's a fair margin for error.

I wired high wattage wirewound resistors to the needed coil combinations, drawing about 30% more than I need. I left this up for 30 minutes. While the resistors were dumping about 60Watts, the transformer just hinted at a rise in temperature after the half hour.


Here's some data and ASCII art showing the transformer coils - note the odd resistance vs voltage on the one tap of 0-130V-160V winding. Apologies if this comes out as a big mess if you're using proportional fonts.

Transformer weight: ~6.5 lbs

Calculated watt rating: ~100W

Calculated max. current for each winding:

- 60V CT winding,            390mA
- 130V winding/tap,     400mA
- 30V winding/tap,      150mA
- 6.3V winding,         2.9A (this would result in over 4W being dumped by  
the secondary coil, so I would not draw that  
much - fortunately I need only 1.5A)



```

                                     )||
                                     )||
30V, 10 Ohms  -----)||  <--- not an error
                                     )||
                                     )||
                                     ||
                                     ||
                                     ||
6.3V, 0.5 Ohms -----)||
                                     )||
                                     ||
                                     ||
                                     ||
-----)||
                                     )||
Primary, 2 Ohms  )||
                  )||
                  )||
                  )||
                  )||
-----)||

```

In order to get 190V or so at 200mA, I have series connected the 60V CT coil with the 130V coil/tap (in phase, of course). This seems to do the trick quite nicely.

So, was I just lucky or is all this reasonable?

Cheers,

--

Chris F. Broadbent

-----

End of GLOWBUGS Digest 250

\*\*\*\*\*